


9DBV0431AKLFT



IDT (Integrated Device Technology)

IC CLOCK BUFFER
Lead free / RoHS Compliant
Integrated Circuits (ICs)

[9DBV0431AKLFT.pdf](#)

Buy Now

Out Stock

0 pcs

Minimum:1

Multiples:100

Manufacturer lead time 10 weeks

Images are for reference only.

See Product Specifications for product details.

If you are interested to buy 9DBV0431AKLFT, Just Email us.

Sales@zeanoit.com

our sales team will reply you within 24 hours

Shopping Process

1

Confirm the product

2

submit the order

3

payment

4

wait for delivery


5

receive the goods

Specifications


Voltage - Supply:	1.7 V ~ 1.9 V
Supplier Device Package:	32-VFQFPN (5x5)
Series:	-
Ratio - Input:Output:	1:4
Packaging:	Tape & Reel (TR)
Package / Case:	32-VFQFN Exposed Pad
PLL:	Yes
Output:	HCSL
Operating Temperature:	0°C ~ 70°C
Number of Circuits:	1
Mounting Type:	Surface Mount
Main Purpose:	Ethernet, PCI Express (PCIe)
Input:	HCSL
Frequency - Max:	137.5MHz
Differential - Input:Output:	Yes/Yes

Related products




9DBV0441AKLFT
IC CLOCK BUFFER
[IDT, Integrated Device Technology Inc](#)

RFQ




9DBV0431AKILF
IC CLOCK BUFFER
[IDT, Integrated Device Technology Inc](#)

RFQ



9DBV0431AKLFT
IC CLOCK BUFFER
[IDT, Integrated Device Technology Inc](#)

RFQ




9DBV0631BKILF
IC CLK BUFFER 1.8V ZDB 40VFQFPN
[IDT, Integrated Device Technology Inc](#)

RFQ




9DBV0431AKLF
IC CLOCK BUFFER 32MLF
[IDT, Integrated Device Technology Inc](#)

RFQ




9DBV0241AKLF
IC CLOCK BUFFER 24MLF
[IDT, Integrated Device Technology Inc](#)

RFQ




9DBV0441AKILFT
IC CLOCK BUFFER
[IDT, Integrated Device Technology Inc](#)

RFQ




9DBV0241AKLFT
IC CLOCK BUFFER
[IDT, Integrated Device Technology Inc](#)

RFQ



9DBV0441AKILF
IC CLOCK BUFFER
[IDT, Integrated Device Technology Inc](#)

RFQ



9DBV0441AKLF
IC CLOCK BUFFER 32MLF
[IDT, Integrated Device Technology Inc](#)

RFQ

Guess You May Looking For



MPC8572LPXAULD
IC MPU MPC85XX 1.333GHZ 1023BGA
[NXP USA Inc.](#)

RFQ



5CSEBA5U23I7N
IC FPGA 145 I/O 672UBGA
[Altera](#)

RFQ



ZLP12840P2032G
IC MCU 8BIT 32KB OTP 20DIP
[Maxim Integrated](#)

RFQ



PIC18F96J65T-I/PT
IC MCU 8BIT 96KB FLASH 100TQFP
[Microchip Technology](#)

RFQ



5CSEMA4U23C7N
IC FPGA 188 I/O 672UBGA
[Altera](#)

RFQ



M2S060TS-FGG484
IC FPGA SOC 60K LUTS
[Microsemi Corporation](#)

RFQ



XCZU2CG-L1SFVC784I
IC FPGA 252 I/O 784FCBGA
[Xilinx Inc.](#)

RFQ



MPC8533VTANGA
IC MPU MPC85XX 800MHZ 783FCBGA
[NXP USA Inc.](#)

RFQ



P1010PSE5DFA
IC MPU Q OR IQ 1.0GHZ 425TEBGA1
[NXP USA Inc.](#)

RFQ



MPC8548EPXAUJD
IC MPU MPC85XX 1.333GHZ 783BGA
[NXP USA Inc.](#)

RFQ