


PI49FCT32805QE



[Diodes Incorporated](#)

IC CLK BUFFER 1:5 133MHZ 20QSOP

Lead free / RoHS Compliant

Integrated Circuits (ICs)

[PI49FCT32805QE.pdf](#)

[Buy Now](#)

part#PI49FCT32805QE is available, see description of PI49FCT32805QE as below .
 use the request quote form to request PI49FCT32805QE price and lead time.
 Buy Electronic Components at zeanoit.com .we are an independent distributor of electronic components with extensive inventory in stock.
 The price and lead time for PI49FCT32805QE depending on the quantity required, availability and warehouse location.Contact us today and our sales team will send you quotation soon.
 Email: sales@zeanoit.com

Out Stock

0 pcs

Minimum:1

Multiples:100

Manufacturer lead time 10 weeks

PRICE

1 pcs	\$4.37
55 pcs	\$3.713
110 pcs	\$3.218
550 pcs	\$2.739
1045 pcs	\$2.31

Shopping Process

1

Confirm the product

2

submit the order

3

payment

4

wait for delivery

5

receive the goods

Specifications

Voltage - Supply:	2.97 V ~ 3.63 V
Type:	Fanout Buffer (Distribution)
Supplier Device Package:	20-QSOP
Series:	49FCT
Ratio - Input:Output:	1:5
Packaging:	Tube
Package / Case:	20-SSOP (0.154", 3.90mm Width)
Output:	CMOS
Operating Temperature:	-40°C ~ 85°C
Number of Circuits:	2
Mounting Type:	Surface Mount
Input:	CMOS
Frequency - Max:	133MHz
Differential - Input:Output:	No/No

Related products

PI49FCT32805H

3.3V, 2 x 1:5 CMOS Clock Driver

[PERICOM](#)

RFQ



PI49FCT32805QEX

IC CLK BUFFER 1:5 133MHZ 20QSOP

[Diodes Incorporated](#)

RFQ

PI49FCT32805Q

3.3V, 2 x 1:5 CMOS Clock Driver

[PERICOM](#)

RFQ



PI49FCT32805HE

IC CLK BUFFER 1:5 133MHZ 20SSOP

[Diodes Incorporated](#)

RFQ



PI49FCT32806H

3.3V, 2 x 1:5 CMOS Clock Driver

[PERICOM](#)

RFQ

PI49FCT32805S

3.3V, 2 x 1:5 CMOS Clock Driver

[PERICOM](#)

RFQ



PI49FCT32803QEX

IC CLK BUFFER 1:7 133MHZ 16QSOP

[Diodes Incorporated](#)

RFQ



PI49FCT32805SE

IC CLK BUFFER 1:5 133MHZ 20SOIC

[Diodes Incorporated](#)

RFQ



PI49FCT32805

3.3V, 2 x 1:5 CMOS Clock Driver

[PERICOM](#)

RFQ




PI49FCT32806

3.3V, 2 x 1:5 CMOS Clock Driver

[PERICOM](#)

RFQ

Guess You May Looking For



P5010NXN1TNB

IC MPU Q OR IQ 2.0GHZ 1295FCBGA

[NXP USA Inc.](#)

RFQ



MAX313LEUE+

IC SWITCH QUAD SPST 16TSSOP

[Maxim Integrated](#)

RFQ




ADG526AKRZ

IC MULTIPLEXER 16X1 28SOIC

[Analog Devices Inc.](#)

RFQ



DG9421DV-T1-E3

IC SWITCH SGL 5V ON/OFF 6-TSOP

[Vishay Siliconix](#)

RFQ



ADG738BRUZ-REEL

IC MUX/DEMUX 8X1 16TSSOP

[Analog Devices Inc.](#)

RFQ



ADG811YRU-REEL

IC SWITCH QUAD SPST 16TSSOP

[Analog Devices Inc.](#)

RFQ



MC14067BCPG

IC MUX/DEMUX 16X1 24DIP

[ON Semiconductor](#)

RFQ



MAX312EUE

IC SWITCH QUAD SPST 16TSSOP

[Maxim Integrated](#)

RFQ



MAX359CWE

IC MULTIPLEXER DUAL 4X1 16SOIC

[Maxim Integrated](#)

RFQ



MC74HC4052ADT

IC MUX/DEMUX DUAL 4X1 16TSSOP

[ON Semiconductor](#)

RFQ