


9DBV0631BKLF



IDT (Integrated Device Technology)

IC CLK BUFFER 1.8V ZDB 40VQFPN

Lead free / RoHS Compliant

Integrated Circuits (ICs)

[9DBV0631BKLF.pdf](#)

Buy Now

We can supply IDT (Integrated Device Technology) 9DBV0631BKLF, use the request quote form to request 9DBV0631BKLF price, IDT (Integrated Device Technology) Datasheet PDF and lead time. Zeano.com is a professional electronic components distributor. With 3+ Million line items of available electronic components can ship in short lead-time, over 250 thousand part numbers of electronic components in stock for immediately delivery, which may include part number 9DBV0631BKLF. The price and lead time for 9DBV0631BKLF depending on the quantity required, availability and warehouse location.

In Stock

490 pcs

Minimum: 1

Multiples: 100

Manufacturer lead time 10 weeks

PRICE

1 pcs	\$3.64
10 pcs	\$3.25
25 pcs	\$2.925
100 pcs	\$2.665
250 pcs	\$2.405
500 pcs	\$2.158
1000 pcs	\$1.82
2500 pcs	\$1.729
5000 pcs	\$1.664

Shopping Process

1

Confirm the product

2

submit the order

3

payment

4

wait for delivery


5

receive the goods

Specifications


Voltage - Supply:	1.7 V ~ 1.9 V
Supplier Device Package:	40-VFQFPN (5x5)
Series:	-
Ratio - Input:Output:	1:6
Packaging:	Tray
Package / Case:	40-VFQFN Exposed Pad
PLL:	Yes with Bypass
Output:	HCSL
Operating Temperature:	0°C ~ 70°C
Number of Circuits:	1
Mounting Type:	Surface Mount
Input:	HCSL
Frequency - Max:	125MHz
Divider/Multiplier:	No/No
Differential - Input:Output:	Yes/Yes

Related products




9DBV0441AKILFT
IC CLOCK BUFFER
[IDT, Integrated Device Technology Inc](#)

RFQ




9DBV0641AKILF
IC CLK BUFFER 1.8V PCIE 40VQFPN
[IDT, Integrated Device Technology Inc](#)

RFQ



9DBV0831AKLF
IC CLOCK BUFFER 48MLF
[IDT, Integrated Device Technology Inc](#)

RFQ




9DBV0441AKLFT
IC CLOCK BUFFER
[IDT, Integrated Device Technology Inc](#)

RFQ



9DBV0831AKILF
IC CLOCK BUFFER
[IDT, Integrated Device Technology Inc](#)

RFQ




9DBV0641AKLF
IC CLK BUFFER 1.8V PCIE 40VQFPN
[IDT, Integrated Device Technology Inc](#)

RFQ




9DBV0831AKILFT
IC CLOCK BUFFER
[IDT, Integrated Device Technology Inc](#)

RFQ




9DBV0631BKILF
IC CLK BUFFER 1.8V ZDB 40VQFPN
[IDT, Integrated Device Technology Inc](#)

RFQ



9DBV0441AKILF
IC CLOCK BUFFER
[IDT, Integrated Device Technology Inc](#)


RFQ



9DBV0441AKLF
IC CLOCK BUFFER 32MLF
[IDT, Integrated Device Technology Inc](#)


RFQ

Guess You May Looking For




USB5533BI5000JZXTR
IC HUB CTRLR USB 3.0 64QFN
[Microchip Technology](#)

RFQ



USB5906/KD
IC HUB CNTRLR USB 3.1 100VQFN
[Microchip Technology](#)

RFQ




LAN9250T/PT
IC ETHERCAT PHY CTRLR 64TQFP
[Microchip Technology](#)

RFQ



DS2480B+T&R
IC LINE DRVR W/SENSOR 1-W 8-SOIC
[Maxim Integrated](#)

RFQ



MAX13082EASA+
IC TXRX RS485/RS422 8-SOIC
[Maxim Integrated](#)

RFQ




ISL8487EIBZ-T
IC TXRX RS485/422 5V ESD 8-SOIC
[Intersil](#)

RFQ



W681512WG
IC VOICEBND CODEC 5V 1CH 20TSSOP
[Nuvoton Technology Corporation of America](#)

RFQ




SN75HVD08DRG4
IC RS485 TXRX 3/5V 8-SOIC
[Texas Instruments](#)

RFQ



ISL31495EIBZ
IC TXRX RS485 FAULT PROT 8SOIC
[Intersil](#)

RFQ



VSC8145XVQ-03
IC TXRX MULTIRATE 16BIT 208-BGA
[Microsemi Solutions Sdn Bhd.](#)

RFQ

