

R5F11MPFAFB#30



Renesas Electronics America
 16BIT MCU RL78/L1A 64K LQFP100
 Lead free / RoHS Compliant
 Integrated Circuits (ICs)

Buy Now

Out Stock

0 pcs

Minimum:1

Multiples:100

Manufacturer lead time 10 weeks

part#R5F11MPFAFB#30 is available, see description of R5F11MPFAFB#30 as below .
 use the request quote form to request R5F11MPFAFB#30 price and lead time.
 Buy Electronic Components at zeanoit.com .we are an independent distributor of
 electronic components with extensive inventory in stock.
 The price and lead time for R5F11MPFAFB#30 depending on the quantity required,
 availability and warehouse location.Contact us today and our sales team will send you
 quotation soon.
 Email: sales@zeanoit.com

Shopping Process

1

Confirm the product

2

submit the order

3

payment

4

wait for delivery

5

receive the goods

Specifications

Voltage - Supply (Vcc/Vdd):	1.8 V ~ 3.6 V
Speed:	24MHz
Series:	RL78/L1A
RAM Size:	5.5K x 8
Program Memory Type:	FLASH
Program Memory Size:	96KB (96K x 8)
Peripherals:	LCD, LVD, POR, PWM, WDT
Oscillator Type:	Internal
Operating Temperature:	-40°C ~ 85°C (TA)
Number of I/O:	79
EEPROM Size:	8K x 8
Data Converters:	A/D 14x12b, D/A 2x12b
Core Size:	16-Bit
Core Processor:	RL78
Connectivity:	CSI, I ² C, LIN, SPI, UART/USART

Related products

RENEASAS

R5F11MPEAFB#50

RL78/L1A 64KB/4KB 100QFP

[Renesas Electronics America](#)

RFQ

RENEASAS

R5F11MMFAFB#30

16BIT MCU RL78/L1A 96K LQFP-80

[Renesas Electronics America](#)

RFQ

RENEASAS

R5F11MMFAFB#50

RL78/L1A 96KB/4KB 80QFP

[Renesas Electronics America](#)

RFQ

RENEASAS

R5F11MPEAFB#30

16BIT MCU RL78/L1A 48K LQFP100

[Renesas Electronics America](#)

RFQ

RENEASAS

R5F11MPGAFB#30

16BIT MCU RL78/L1A 128K LQFP100

[Renesas Electronics America](#)

RFQ

RENEASAS

R5F11MPGAFB#50

RL78/L1A 128KB/4KB 100QFP

[Renesas Electronics America](#)

RFQ

RENEASAS

R5F21102FP

[RENEASAS](#)

RFQ



R5F21102DFP#U0

IC MCU 16BIT 8KB FLASH 32LQFP

[Renesas Electronics America](#)

RFQ

RENEASAS

R5F11MPFAFB#50

RL78/L1A 96KB/4KB 100QFP

[Renesas Electronics America](#)

RFQ

RENEASAS

R5F11MMEAFB#50

RL78/L1A 64KB/4KB 80QFP

[Renesas Electronics America](#)

RFQ

Guess You May Looking For



UC3871DW

IC FLUORESCENT LAMP DRVR 18-SOIC

[Texas Instruments](#)

RFQ




VNQ5E250AJ-E

IC DVR QUAD HIGH SIDE POWERSO16

[STMicroelectronics](#)

RFQ



BD5357G-TR

IC DETECTOR VOLT 5.7V CMOS 5SSOP

[Rohm Semiconductor](#)

RFQ



XC6118N11DGR-G

IC SUPERVISOR 1.1V 4-USP

[Torex Semiconductor Ltd](#)

RFQ



S-80819CLNB-B6ET2U

IC VOLT DETECTOR 1.9V SC-82AB

[SII Semiconductor Corporation](#)

RFQ



ADR5040AKSZ-REEL7

IC VREF SHUNT 2.048V SC70

[Analog Devices Inc.](#)

RFQ



MAX1837EUT33#TG16

IC REG BUCK 3.3V 0.25A SOT23-6

[Maxim Integrated](#)

RFQ




TPS76550D

IC REG LDO 5V 0.15A 8SOIC

[Texas Instruments](#)

RFQ



MIC5239-3.3YMM

IC REG LDO 3.3V 0.5A 8MSOP

[Microchip Technology](#)

RFQ



MIC5335-SNYMT-TR

IC REG LDO 3.3V/2.85V 0.3A 6TMLF

[Microchip Technology](#)

RFQ