


MPC9350FA



[NXP Semiconductors / Freescale](#)

IC CLOCK GENERATOR PLL LV 32LQFP

Contains lead / RoHS non-compliant

Integrated Circuits (ICs)

[MPC9350FA.pdf](#)

[Buy Now](#)

We can supply NXP Semiconductors / Freescale MPC9350FA, use the request quote form to request MPC9350FA price, NXP Semiconductors / Freescale Datasheet PDF and lead time. Zeanoit.com is a professional electronic components distributor. With 3+ Million line items of available electronic components can ship in short lead-time, over 250 thousand part numbers of electronic components in stock for immediate delivery, which may include part number MPC9350FA. The price and lead time for MPC9350FA depending on the quantity required, availability and warehouse location.

Shopping Process

1

Confirm the product

2

submit the order

3

payment

4

wait for delivery

5

receive the goods

Specifications

| | |
|-------------------------------------|---|
| Voltage - Supply: | 2.375 V ~ 3.465 V |
| Type: | Clock Generator, Fanout Distribution, Multiplexer |
| Supplier Device Package: | 32-LQFP (7x7) |
| Series: | - |
| Ratio - Input:Output: | 3:9 |
| Packaging: | Tray |
| Package / Case: | 32-LQFP |
| PLL: | Yes with Bypass |
| Output: | LVC MOS |
| Operating Temperature: | -40°C ~ 85°C |
| Number of Circuits: | 1 |
| Mounting Type: | Surface Mount |
| Input: | LVC MOS, Crystal |
| Frequency - Max: | 200MHz |
| Divider/Multiplier: | Yes/No |
| Differential - Input:Output: | No/No |

Related products



MPC9350AC

IC PLL CLOCK DRIVER LV 32-LQFP
[IDT, Integrated Device Technology Inc](#)

RFQ



MPC9350AC

IC PLL CLOCK DRIVER LV 32-LQFP
[NXP USA Inc.](#)

RFQ



MPC9350ACR2

IC PLL CLOCK DRIVER LV 32-LQFP
[IDT, Integrated Device Technology Inc](#)

RFQ



MPC9351D

in stock
[FREESCALE](#)

RFQ



MPC9350

[FREESCALE](#)

RFQ



MPC9351ACR2

IC PLL CLOCK DRIVER LV 32-LQFP
[IDT, Integrated Device Technology Inc](#)

RFQ



MPC9351AC

IC PLL CLOCK DRIVER LV 32-LQFP
[IDT, Integrated Device Technology Inc](#)

RFQ



MPC9351

in stock
[FREESCALE](#)

RFQ



MPC9331FAR2

IC CLOCK GEN 1:6 PLL LV 32-LQFP
[NXP USA Inc.](#)

RFQ



MPC9351AC

IC PLL CLOCK DRIVER LV 32-LQFP
[NXP USA Inc.](#)

RFQ


Guess You May Looking For



SN65MLVD200ADR

IC M-LVDS LINE DVR/RCVR 8-SOIC
[Texas Instruments](#)


RFQ



MAX485ECSA+

IC TXRX RS485/RS422 8-SOIC
[Maxim Integrated](#)

RFQ



TLK105LRHBT

IC TXRX IND ETHERNET PHY 32QFN
[Texas Instruments](#)

RFQ



MIC2551AYTS-TR

IC USB TRANSCEIVER 14-TSSOP
[Microchip Technology](#)

RFQ



SP3075EMN-L/TR

IC TXRX RS485/RS422 ESD 8SOIC
[Exar Corporation](#)

RFQ



TL3695PG4

IC DIFF BUS TXRX BI-DIR 8-DIP
[Texas Instruments](#)

RFQ



MAX3956AETJ+

IC TX 11.3GBPS 32TQFN
[Maxim Integrated](#)

RFQ



MAX3226ECUE+T

IC TXRX RS232 250KBPS SD 16TSSOP
[Maxim Integrated](#)

RFQ



LMS202EIMWX/NOPB

IC TXRX RS232 230KBPS 16SOIC
[Texas Instruments](#)

RFQ



NMF3000FCT1G

IC LINE FLTR AUDIO/ESD 9FLIPCHIP
[ON Semiconductor](#)

RFQ